APPENDIX D Field Notes and Field Forms

DAILY FIELD REPORT MMRP SITE INSPECTION

NTRACT NO		W912DY-04-D-0005	DELIVERY ORDER	NO	8000
B NO:		744647-70000	DATE/DAY:		9-Apr-08
E NAME:		Switzerland Bombing Target	REPORT NO:		1
SACE DISTRIC	CT:	CESAJ	SHEET:		1
ATHER:		Sunny; Low of 63; High of 77.	<u></u>		
ORK IN PROG	RESS OR COMP	LETED:			
1. Mobili	zation/Demob	ilization			CUMULATIVE
80	Miles Driven				80
0/0	Number of Flig	ghts/Miles Flown			0/0
3	Personnel:				3
2 Pagan	naissance Det	aile			<u> </u>
27.100	Linear Feet:	alis			27,100
27,100	Discussion -	The Parsons Field Team collected	27 100 feet of walked OR		21,100
	Discussion -	The Faisons Field Feath Collected	27,100 leet of walked QIV.		
3. MC Sa	ampling Detail	<u> </u>			_
3	Soil and Sedim				3
0	Water Samples				0
		s: See Attached DQCR			
4. QC Ac	tivities				_
0	Soil and Sedim	•			0
0	Water Samples				0
5. QA Ac	tivitios				<u> </u>
0	Soil and Sedim	ent Samples			0
0	Water Samples	•			0
<u> </u>	•	s: No QA split for this site			`
		•			
6. Safety	Activities				
Safety brief	ing covered MEC/	MD, route to the hospital, and poise	onous plants and animals.		_
		PARSONS WORKFORCE		On-site	Tailgate Brief
Daraona ET	L - Erich Stedma	20	Cell Phone: 678-595-8650	Yes/No Yes	Yes/No Yes
	O Technician/SSI		Cell Phone: 843-761-6592	Yes	Yes
	am Member- Stev		Cell Phone: 919-606-0381	Yes	Yes
		VISITORS			1.22
Chuck Farm	ner		Cell Phone: 386-623-6064	Yes	No
Jeff Ulmer			Cell Phone: 770-634-8561	Yes	Yes
FOURDMEN	IT . 10T				
EQUIPMEN			111.00		
Schonstedt,	, ਤ Kino GPS, Lap	top, Trimble, Camera, Lamont Turb	bidity Meter and U-22 water quality r	neter.	
ADDITION	AL INCORMATION	ı.			
ADDITIONA	AL INFORMATIO		recorded in PDA/Logbook		
ACTIVITIES	S SCHEDULED F	OR NEXT WORK DAY:	recorded III i DA/Logbook		
		continue to collect QR and samples	S.		
		-			
-	FOR PROJECT A	CTION:			
None					
ACCIDENTS F	REPORTED TODAY:	0			
ACCIDENTS T		0	Prepared By Field T	eam Leader:	Erich Stedman

DAILY CONTRACTOR QUALITY CONTROL REPORT

Contract Number: W912DY-04-D-0005

Delivery Order: 8000

Project Name: MMRP FUDS SI 744647-70000 **Project Number:**

Switzerland Bombing Target Site Location:

Date: 9-Apr-08

Activities Conducted:

The Parsons site visit team (SVT) collected 27,100 feet of walked QR and collected three soil samples. At 11:50 am, the SVT met up with Chuck Farmer who is a representative for the land owner, Anderson Columbia. Mr. Farmer was scheduled to meet us at 9:00 am to let us onto the property, but he called back saying he was running late. Mr. Farmer questioned the SVT about exactly what we will be doing, and we explained to him what the government is doing with all the FUDS and what we will be doing on his property. After talking to us, he seemed much more at ease. He told us his company had spent \$5,000,000 on the cleanup of 800 acres from 2003 through 2005. The company that did the cleanup is Ordnance Explosives Remediation. The SVT gave Parsons' address and the Field Team Leader as a contact to Mr. Farmer so he could mail a copy of the final report that was given to them after the cleanup. He said that they also collected soil samples and water samples from the target. The SVT asked him if he knew of the ordnance that was found, and he stated that there were 3-lb. practice bombs, 25-lb. practice bombs, and Scar 2.75" practice rockets.

He also stated that many thousands of pounds of practice bomb scrap was hauled off the site. The SVT walked the two outer loops of QR. The QR had to be somewhat adjusted due to vegetation and swamp. The QR north of Greenbrier Road where soil sample SS-0 is located could not be walked due to lack of ROE. Soil sample SS-05 will be moved and collected tomorrow. No MEC/MD was observed today. The Schonstedt was checked on a metal all-purpose tool before work started and after work was completed. Samples are being held on ice for later shipment.

Work Planned:

The Parsons Team will collect QR and samples from the MRS and Remaining Lands.

Field Instrument Measurements (list or provide attachment):

Water Sampling Location:	Temp (°C):	Cond (mS/cm)	Turb (NTU):	pH (s.u.):
NA				

Equipment Calibrations (list or provide attachment):NA

List all field and quality control samples collected (list or provide attachment):

Sample ID	Media	Time	Analysis	Shipment Date	Lab	Comments
SBT-RL-SS-02-07	Soil	0957	Metals, Explosives	4/10/2008	TA	ambient
SBT-MRS01-SS-02-06	Soil	1257	Metals, Explosives	4/10/2008	TA	
SBT-MRS01-SS-02-02	Soil	1446	Metals, Explosives	4/10/2008	TA	

Departures from approved SAP:

Holding samples on ice for later shipment.

Instructions given by government personnel:

None

Check all attachments

Field sampling forms (in separate submittal)

Field-generated analytical results

Chain-of-custody forms (in separate submittal)

Signed by: Erich Stedman

Name Erich Stedman, FTL Date: 9-Apr-08

Mobile: 678-595-8650 Office#: 678-969-2428 Phone

Copies sent to:

ent to:		
Deborah Walker (EM CX)	Charlie Fales (CESAJ)	
Heidi Novotny (EM CX)	Chris Cochrane (CEHNC)	
Doug Garretson (CEHNC)	Michael D'Auben (CEHNC)	
Don Silkebakken (Parsons PM)	Laura Kelley (Parsons DPM)	
Ivie Nitschke (Parsons)	Tammy Chang (Parsons)	

DAILY FIELD REPORT MMRP SITE INSPECTION

ONTRACT NO	. <u>W912DY-04-D-0005</u> 744647-70000	DELIVERY ORDER DATE/DAY:	NO	0008 10-Apr-08
TE NAME:	Switzerland Bombing Target	REPORT NO:		2
SACE DISTRIC	CESAJ	SHEET:		1
EATHER:	Sunny; Low of 65; High of 77.			
	RESS OR COMPLETED:			
	zation/Demobilization			CUMULATIVE
70	Miles Driven			150
2/350	Number of Flights/Miles Flown Personnel:			2/350
3	Personner:			<u> </u>
2. Recon	naissance Details			_
10,200	Linear Feet:			37,300
	Discussion - The Parsons Field Team collected 10,200 fe	eet of walked QR.		
3 MC Sa	ampling Details			_
5. WC 36	Soil and Sediment Samples			9
2	Water Samples			2
	Sampling Notes: See Attached DQCR			
				_
4. QC Ac	tivities			_
6	Soil and Sediment Samples			6
3	Water Samples			3
	Sampling Notes: See Attached DQCR			
				<u> </u>
5. QA Ac				
2	Soil and Sediment Samples			2
1	Water Samples			1
	Sampling Notes: See Attached DQCR			_
				_
-	Activities			_
Safety brief	ing covered MEC/MD, emergency procedures, and slips, trip	s, and falls.		
	PARSONS WORKFORCE		On-site Yes/No	Tailgate Brief Yes/No
Parsons FT	L - Erich Stedman Cell	Phone: 678-595-8650	Yes	Yes
		Phone: 843-761-6592	Yes	Yes
		Phone: 919-606-0381	Yes	Yes
	VISITORS			
None				
EQUIPMEN	IT LIST:			
	, 3 Rino GPS, Laptop, Trimble, Camera, Lamont Turbidity M	eter and I I-22 water quality	meter	
SCHOHSIEUL	, o Kino OFO, Laptop, Trimbie, Camera, Lamont Turbidity Mi	eter and 0-22 water quality	metel.	
ADDITION	AL INFORMATION:			
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	All other site details recorde	ed in PDA/Logbook		
ACTIVITIES	S SCHEDULED FOR NEXT WORK DAY:			
The Parson	s Field Team has completed all field work at Switzerland Bo	mbing Target.		
REQUEST	FOR PROJECT ACTION:			
None				
ACCIDENTS F	REPORTED TODAY: 0 O DATE: 0	Prepared By Field T	eam Leader:	Erich Stedman
		-	-	-

DAILY CONTRACTOR QUALITY CONTROL REPORT

Contract Number: W912DY-04-D-0005

Delivery Order: 0008

Project Name: MMRP FUDS SI Project Number: 744647-70000

Site Location: Switzerland Bombing Target

Date: 10-Apr-08

Activities Conducted:

The Parsons site visit team (SVT) collected 10,200 feet of walked QR, six soil and sediment samples, and two surface water samples. The SVT collected the remaining QR; however, QR was adjusted somewhat due to vegetation and swamp. The third QR loop was modified severely due to the presence of a housing subdivision without ROE. Surface water and sediment samples SW-01, SW-02, SD-01, and SD-02 were collected from the same creek as originally planned but were moved a few hundred feet due to access issues Soil sample SS-05 was moved because of a lack of ROE for the original sample location. The SVT found an area with a few subsurface anomalies and a single suspension lug from an MK-76 practice bomb. Soil sample SS-04 was moved a couple hundred feet from its planned location to what appeared to be a old scrap wood pile. A couple pieces of MK-23 practice bombs were observed along with unidentifiable metal. The Parsons Geographic Lead was contacted prior to the relocating of all samples. The Schonstedt was checked on a metal all-purpose tool before work started and after work was completed. Four coolers were shipped via FedEx overnight; three to TA and one to GPL.

Work Planned:

The Parsons Field Team has completed all field work at Switzerland Bombing Target.

Field Instrument Measurements (list or provide attachment):

Water Sampling Location:	Temp (ºC):	Cond (mS/cm)	Turb (NTU):	pH (s.u.):
SBT-MRS01-SW-01	17.74	0.311	8.24	7.21
SBT-RL-SW-02	20.11	7.44	10.56	7.6

Equipment Calibrations (list or provide attachment):

pH - 4.01, Conductivity - 4.49, Temperature - 19.22, Turbidity - 10.0

List all field and quality control samples collected (list or provide attachment):

				Shipment		
Sample ID	Media	Time	Analysis	Date	Lab	Comments
SBT-MRS01-SW-01	Water	0854	Metals, Explosives	4/10/2008	TA	MS/MSD
SBT-MRS01-SW-01 QA	Water	0854	Metals, Explosives	4/10/2008	GPL	QA Sample
SBT-MRS01-SW-03	Water	0822	Metals, Explosives	4/10/2008	TA	FD of SBT-MRS01- SW-01
SBT-MRS01-SD-01	Sediment	0912	Metals, Explosives	4/10/2008	TA	MS/MSD
SBT-MRS01-SD-01 QA	Sediment	0912	Metals, Explosives	4/10/2008	GPL	QA Sample
SBT-MRS01-SD-03	Sediment	0831	Metals, Explosives	4/10/2008	TA	FD of SBT-MRS01- SD-01
SBT-RL-SW-02	Water	0955	Metals, Explosives	4/10/2008	TA	ambient
SBT-RL-SD-02	Sediment	0958	Metals, Explosives	4/10/2008	TA	ambient
SBT-RL-SS-02-01	Soil	1013	Metals, Explosives	4/10/2008	TA	ambient
SBT-MRS01-SS-02-03	Soil	1039	Metals, Explosives	4/10/2008	TA	
SBT-MRS01-SS-02-05	Soil	1120	Metals, Explosives	4/10/2008	TA	MS/MSD
SBT-MRS01-SS-02-05 QA	Soil	1120	Metals, Explosives	4/10/2008	GPL	QA Sample
SBT-MRS01-SS-02-08	Soil	1101	Metals, Explosives	4/10/2008	TA	FD of SBT-MRS01- SS-02-05
SBT-MRS01-SS-02-04	Soil	1142	Metals, Explosives	4/10/2008	TA	

Departures from approved SAP:

Surface water and sediment samples SW-01, SW-02, SD-01, and SD-02 and soil samples SS-04 and SS-05 were moved from their planned locations.

Instructions	aiven l	v government	personnel.

None

Check all	attachments	
	Field sampling forms (in separate submittal) Field-generated analytical results	
X	Chain-of-custody forms (in separate submittal)	
Signed by:	Erich Stedman	
Name	Erich Stedman, FTL	
Date:	10-Apr-08	
Phone	Mobile: 678-595-8650	Office#: 678-969-2428
Copies ser	nt to:	
	Deborah Walker (EM CX)	Charlie Fales (CESAJ)
	Heidi Novotny (EM CX)	Chris Cochrane (CEHNC)
	Doug Garretson (CEHNC)	Michael D'Auben (CEHNC)
	Don Silkebakken (Parsons PM)	Laura Kelley (Parsons DPM)
	Ivie Nitschke (Parsons)	Tammy Chang (Parsons)